

Riverina- PCG Report December 2018

Project Team

Developer	Australia Xing One Pty Ltd
Contractor	Australia Cenvic Construction
Architect	Peddle Thorp Architect
Structural Engineer	Bonacci Group
Services Engineer	JBA Consultant
Building Surveyor	BSGM

Monthly Project Progress

Structure

- Concrete infill of Alimak Hoist penetration from Level 1 to Level 6 of Tower E.
- Concrete infill of Alimak Hoist penetration from ground Level to Level 2 of Tower C.
- Concrete structure of kerb around main core from Level 1 to Level 5 of Tower E has been completed.
- Structural concrete patching caulking was completed in car park areas in podium levels.
- Block wall in car park area at podium Level 1&2 has been completed.

Façade

- Window wall: Installation of all window walls at Level 5 of Tower C,D&E.
- Corten cladding: Installation in Level 2&3 has been completed in Tower C,D&E.
- Sliding door: external caulking of Level 3&4 has been completed in Tower C,D&E.
- Fold-up door: Install frame at ramp entrance of Tower C.

Services

- Plumbing: Install stormwater and sewer pipes at Level 12 of Tower D; Install cold and hot water pipes & taps fit out at podium level 1.
- Mechanical: Install ducts, plenum boxes on window at podium level 4&5 of Tower C, D&E.
- Electrical: Cut cable and fit out at podium level 1 and rough-in at podium level 3&4.
- Fire service: Install sprinkler pipes and heads at podium level 4.
- Lift: On-going Installation of tower lift in Tower C.

Interior Fit-out

- Plaster: Level to level 4 apartment plaster wall completed.
- Kitchen& Bath: Level 1 Show screen and wardrobe Installed.
- Waterproofing of balcony floor at Level 1 has been completed.
- Laundry door installation has been completed from podium Level 1 to 3.

21 December 2018

Photos:
Structural





Façade



21 December 2018

Service



Interior Fit-out

